0005

From:

April Abate

To:

Vicky Miller

CC:

OGMCOAL@utah.gov 6/17/2009 10:09 AM

Date: Subject:

Banning Loadout - Quarterly Monitoring Report

Place:

OGMCOAL@utah.gov **Attachments:** 0005.pdf; April Abate.vcf

Hello Vicky,

Attached is your quarterly water monitoring report for the Banning Loadout site. Not much to report here.

Please contact me if you have any questions or comments.

Sincerely,

April

April A. Abate

Environmental Scientist II Division of Oil, Gas and Mining 1594 W. North Temple, Suite 1210 Salt Lake City, Utah 84114-5801 T: 801.538.5214 F: 801.359.3940 M: 801.232.1339

()utgoing c/001/0034 &

K

WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

June 9, 2009

TO:	Internal File			
THRU:	Jim Smith, Permit Supervisor			
FROM:	Jim Smith, Permit Supervisor April Abate, Environmental Scientist II Caa 6-10-09			
RE:	2009 First Quarter Water Monitoring, Canyon Fuel Company, Banning Siding Loadout, C/007/0034, WQ09-1, Task ID #3237			
The Banning Siding Loadout has been in temporary cessation since 2000.				
Pertinent water monitoring requirement information is in the MRP in Sections 731.210, and 731.220.				
1. Was data	submitted for all of the MRP required sites? YES 🔀 NO 🗌			
Springs – Loado	The Permittee is not required to monitor any springs at the Banning Siding out.			
Streams – The Permittee is not required to monitor any streams at the Banning Siding Loadout.				
Wells-	During temporary cessation, the Permittee is required to sample the "Truck Dump Sump during the "late fall."			
	The Truck Dump Sump was not monitored this quarter.			
LIDDES				

There are two active UPDES sites at the Banning Siding Loadout. They are both under the permit #UTG040011, and are the primary and emergency spillways for

4. 9 (4.4)

Page 2 C/007/0034-WQ09-1 Task ID #3237 June 9, 2009

the sedimentation pond. The Permittee is required to monitor each UPDES site monthly.

The Permittee monitored and reported the essential data for all UPDES sites as required during this quarter. None of the UPDES sites recorded any flow during the period.

2.	Were all required parameters reported for each site?	YES	№ 🗌
	Not applicable this quarter		
3.	Were any irregularities found in the data?	YES 🗌	NO 🗌
	Not applicable this quarter		
4.	On what date does the MRP require a five-year re-samp	oling of baseline	water data.

The MRP does not contain a commitment for re-sampling of baseline water data.

5. Based on your review, what further actions, if any, do you recommend?

No further actions are required at this time.

O:\007034.BAN\WATER QUALITY\WQ09-1.DOC